

Customer Service Bulletin

SLM Electronics, Inc. Saint Louis, Missouri

Mar. 17, 1999

CSB0010

Units Affected:

Model

Ampeg SVT-4PRON

Serial Number

All prior to ASDK60001

Purpose:

Rear screen and owners manual have incorrect information for the Biamp connectors.

Recommended Action:

1. Call the SLM Electronics Factory Service Center at **1-800-738-7563** and request one each of the following parts:

Part # 47-617-99	SVT4PRON Rear label for Biamp Fix
Part # 47-617-03	SVT4PRON Manual 6-98
2. Separate the label into two parts. Refer to the photo below for the location for each label and apply them to the rear chassis as shown. Line labels up so they completely cover the existing text, without overlapping onto any nearby graphics. Press labels firmly into place.



3. Discard old manual (part # 47-617-02), if applicable. Include replacement manual (#47-617-03) with unit.

SLM Electronics, A Division of St. Louis Music, Inc.
11880 Borman Drive, St. Louis, MO 63146
Phone (314) 569-0141
Service Department: Phone (800) 738-7563; Fax (314) 567-7278