User Name:

Password:

Language Selection

English ▼

Log In

About

Model: Cisco DPC3008

Vendor: Cisco
Hardware Revision: 1.0

MAC Address: 7c:b2:1b:13:08:1e

Bootloader Revision: 2.3.1_R3

 Current Software Revision:
 d3000-c2000r5593-160113a

 Firmware Name:
 d3000-c2000r5593-160113a.bin

Firmware Build Time: Jan 13 11:21:00 2016

Cable Modem Status: Operational

Cable Modem State

DOCSIS Downstream Scanning:

DOCSIS Ranging:

DOCSIS DHCP:

Completed

DOCSIS TFTP:

Completed

DOCSIS Data Reg Complete:

DOCSIS Privacy:

Completed

Completed

Completed

Completed

Downstream Channels

	Power Level:	Signal to Noise Ratio:
Channel 1:	14.1 dBmV	42.9 dB
Channel 2:	13.4 dBmV	42.2 dB
Channel 3:	13.9 dBmV	42.4 dB
Channel 4:	14.8 dBmV	42.6 dB
Channel 5:	14.3 dBmV	41.9 dB
Channel 6:	14.6 dBmV	42.5 dB
Channel 7:	14.3 dBmV	42.1 dB
Channel 8:	13.1 dBmV	41.4 dB

Upstream Channels

Power Level:
Channel 1: 40.5 dBmV
Channel 2: 0.0 dBmV
Channel 3: 0.0 dBmV
Channel 4: 0.0 dBmV