Customer Service Bulletin

SLM Electronics, Inc. Saint Louis, Missouri, USA

March 26, 2001 #CSB0016

Units Affected:

Model	Serial Numbers		
GX65U	BOEUMA0001	through	BOEUMA0015
	BOEUM00001	through	BOEUM00105
GX65W	BOBWM00001	through	BOBWM00300
	BOBWMA0001	through	BOBWMA0155
	BOBWM00406	through	BOBWM00460
	BOBWM00301	through	BOBWM00405
GX212U	BODUMA0001	through	BODUMA0010
	BODUM00001	through	BODUM00065
GX212W	BOCWMA0001	through	BOCWMA0105
	BOCWM00001	through	BOCWM00085

Purposes:

- (1) Some units have been shipped with defective caster sockets, resulting in breakage to the sockets as well as casters falling out of the sockets.
- (3) Some units have defective rubber feet, resulting in loss of the feet.

Recommended Actions:

- (1) Replace the existing caster sockets with those supplied.
- (2) Replace the existing rubber feet with those supplied.

Tools Needed:

• #2 phillips screwdriver

Corrective Action:


- (1) Unpack the amplifier and place it on the work surface so the bottom of the cabinet is facing up.
- (2) Remove the caster sockets ("A") from the bottom of the cabinet.
- (3) Remove the rubber feet ("B") from the bottom of the cabinet.



Customer Service Bulletin

SLM Electronics, Inc. Saint Louis, Missouri, USA

- (4) Install the supplied caster sockets, flat side up (as shown to the right) onto the cabinet. Rotate each caster socket 45° from its original position so the screws thread into fresh wood. (Drill 1/16" pilot holes if desired.) Do not overtighten the screws.
- (5) Install the supplied rubber feet, flat side down (as shown to the right) onto the cabinet. Do not overtighten the screws. (The feet will compress slightly when the screws are tightened.)



Repacking the Units:

- (1) Clean the unit as needed and wrap it in its protective plastic bag.
- (2) Ensure that all original packing materials and literature are repacked in their original locations.
- (3) Make absolutely certain to match the unit's serial number to that on the shipping carton.
- (4) Reseal the inner carton prior to re-sealing the outer carton.

