

SLM Electronics

A Division of St. Louis Music, Inc.

11880 Borman Dr
St. Louis, MO 63146
Phone 314 569 0141

Service Department
Phone 800 738 7563
Fax 314 567 7278

June, 1998

Customer Service Bulletin

CSB0004

Units Affected:

- | | |
|-------|--|
| B-15 | Serial Numbers: from AJYDJ60001 through AJYDJ60017
from AJYDJ70013 through AJYDJ70034
from AJYDJ80001 through AJYDJ80008 |
| B-15J | Serial Numbers: from AJZJJ70001 through AJZJJ70005 |
| B-15W | Serial Numbers: from AKAWJ70001 through AKAWJ70055 |

Concern:

The color labels at terminals **J40** (GREEN), and **J41** (ORANGE) are misidentified on the printed circuit board. Terminal J39 (BLACK) is correct and is of no concern. These are connect points for 3 wires from the audio output transformer secondary. These units **are** however wired correctly and do function properly. This could cause some confusion in servicing these units.

Corrective Action:

The proper wiring is as follows: (see drawing below)

GREEN wire to **J 41**; **ORANGE** wire to **J 40**;

(BLACK wire to **J 39** no correction necessary.)

